

File Options

INPUT

V LINE - volts 300 455
 [Progress Bar]

TEMP - °C 0 100
 [Progress Bar]

Power Cube Software Version : 1.1 - SN : 9999999999

STATUS OK PHASE OK WATER OK

OUTPUT


V COIL - % 0 100
 [Progress Bar]

I SUPPLY - % 0 100
 [Progress Bar]

I OUT - % 0 100
 [Progress Bar]

POWER - % 0 100
 [Progress Bar]

Frequency - Khz 750 1000
 [Progress Bar]



TRACE MEMORY OFF CLEAR TRACES AUTO FULL

EXPERT ADVICE

The power absorbed by the piece is low. Reduce the distance between the piece and the coil.

BEGIN TEST END TEST

CONTROL

POWER - % [Progress Bar]
 [Progress Bar] START STOP

GENERATOR DISPLAY WORKING TIME - h HEATING TIME - h

-H1 000516 000022 Exit